

ERRATA

The initial paper failed to mention cases where some narrow lower parts of a cavity may become unsupported, requiring extra bridge supports. We have updated the most complete version of this work in order to describe these cases, as well as how to detect them and add a support below.

Please see our updated technical report: <https://hal.inria.fr/hal-01570330>